



5/645/029

# United States Department of the Interior

BUREAU OF LAND MANAGEMENT  
Salt Lake District Office  
2370 South 2300 West  
Salt Lake City, Utah 84119



IN REPLY REFER TO:

U27-89-10N  
3809  
(U-027)

DEC 17 1991

Mr. Sidney K. Hullinger  
McFarland and Hullinger  
P. O. Box 238  
Tooele, Utah 84074

Dear Mr. Hullinger:

Thank you for your letter dated November 29, 1991 regarding your limestone quarry, as per mining notice U27-89-10N, located in the Boulter Springs area, in T. 9 S., R. 4 W., section 35.

This mining notice has been reopened; however after reviewing your notice, it was apparent that operations have not been conducted as described in the notice. Under "proposed operations" it was stated that "mining will be on twenty foot benches...". A single high wall was observed during the field examination. The high wall is unstable and is a safety hazard.

A joint field inspection is required to review your operation. After the field examination, and prior to resuming operations, an amendment to your notice is required that addresses the above noted stability and safety issues.

Thank you for your cooperation. Please contact Maria Soriano or Steve Brooks at 977-4300 to arrange the field examination.

Sincerely,

*Howard Hedrick*

Howard Hedrick  
Pony Express Resource Area Manager

cc: Wayne Hedberg, UDOGM

RECEIVED

DEC 18 1991

DIVISION OF  
OIL GAS & MINING